

FIG. 1




FIG. 2A




FIG. 2B




FIG. 2C




FIG. 2D




FIG. 2E

Decreasing Rigidity of Cross-linked Materials




FIG. 2H




FIG. 2F




FIG. 2G




FIG. 2N




FIG. 2I




FIG. 2J




FIG. 2K

204750-11024001





FIG. 2L





FIG. 2M

204707402400T




FIG. 3A




FIG. 3B




FIG. 4




FIG. 5A




FIG. 5B









FIG. 5C





$$T_1 > T_2$$

FIG. 7A



$$T_3 < T_4$$

FIG. 7B

20171011024001




FIG. 8




FIG. 9




FIG. 10